

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: RDs Party Shop Inc 1480 Continental Dr Butte MT 59701 Phone: (406) 782-4255

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4700386	RDs Party Shop Inc	848 W Park St	Butte	59701	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
5 / 05 Currently In Use	4425	9/1/1998 07 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
6 / 06 Currently In Use	4426	9/1/1998 07 / No	Gasoline 6,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
7 / 07 Currently In Use	4427	9/1/1998 07 / No	Diesel 5,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Kids Behavioral Health of MT 55 Basin Creek Road Butte MT 59701 Phone: (406) 494-4183

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4700458	Childrens Comprehensive Services	55 Basin Creek Road	Butte	59701	(406) 494-4183

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
1 / 01 Currently in Use	3974	6/22/1987 19 / No	Diesel 2,000	Fiberglass Reinforced Plastic None	Copper Double-Walled/Non-Corro	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I <input checked="" type="radio"/> K L</div> </div>	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Walsh Plumbing & Heating 1716 Harrison Ave Butte MT 59701 Phone: (406) 782-5404

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4700542	Walsh Engineering Co	1716 Harrison Ave	Butte	59701	(406) 782-5404

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
Status									Spill/Overl/C
2 / 02 Currently in Use	2241	8/25/1989 16 / No	Gasoline 1,000	STI-P3 None	Galvanized Steel Cathodically Protected	Safe Suction	<input checked="" type="radio"/> B <input type="radio"/> C <input type="radio"/> D <input type="radio"/> E <input type="radio"/> F <input type="radio"/> G <input type="radio"/> H <input type="radio"/> I <input type="radio"/> J <input type="radio"/> K <input type="radio"/> L	<input type="radio"/> B <input type="radio"/> D <input type="radio"/> E <input type="radio"/> F <input type="radio"/> G <input type="radio"/> H <input type="radio"/> I <input checked="" type="radio"/> J <input type="radio"/> K <input type="radio"/> L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Sutey Oil Co Inc 2000 Holmes Ave Butte MT 59701 Phone: (406) 494-2305

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4700942	Thriftway Super Stop 5	901 E Front St	Butte	59701	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 05 Currently in Use	2059	8/1/1994 11 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
2 / 06 Currently in Use	2060	8/1/1994 11 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
3 / 07 Currently in Use	2061	8/1/1994 11 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Montana Department of Transportation Deadhead Helena MT 59620 Phone: (406) 444-6200

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4701062	MDOT Butte District Headquarters	3751 Wynne Ave	Butte	59701	

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material		Tank Release Detection	FR Met																									
Status				Secondary Option	Secondary Option	Piping Type	Piping Release Detection	Spill/Overl/C																									
8 / 08 Currently in Use	2937	8/1/1994 11 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td>B</td><td></td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L		B			D	E	F	G	H	I	J	K	<input checked="" type="radio"/>	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																						
	B			D	E	F	G	H	I	J	K	<input checked="" type="radio"/>																					
9 / 09 Currently in Use	2938	8/1/1994 11 / No	Diesel 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td>B</td><td></td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L		B			D	E	F	G	H	I	J	K	<input checked="" type="radio"/>	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																						
	B			D	E	F	G	H	I	J	K	<input checked="" type="radio"/>																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Mount Moriah Cemetery Association 2415 S Montana St Butte MT 59701 Phone: (406) 782-1778

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4701705	Mount Moriah Cemetery Association	2415 S Montana St	Butte	59701	

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
2 / 02 Currently in Use	1720	7/1/1996 10 / No	Gasoline 300	STI-P3 None	Bare Steel Double-Walled/Non-Corro	Safe Suction	<div> <input checked="" type="radio"/> B <input type="radio"/> C <input type="radio"/> D <input type="radio"/> E <input type="radio"/> F <input type="radio"/> G <input type="radio"/> H <input type="radio"/> I <input type="radio"/> J <input type="radio"/> K <input type="radio"/> L </div>	<div> <input type="radio"/> B <input type="radio"/> D <input type="radio"/> E <input type="radio"/> F <input type="radio"/> G <input type="radio"/> H <input type="radio"/> I <input checked="" type="radio"/> J <input type="radio"/> K <input type="radio"/> L </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Bigheads Inc 910 S Montana St Butte MT 59701 Phone: (406) 723-7306

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4701835	Sheas Auto Repair	910 S Montana St	Butte	59701	(406) 723-7306

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
7 / 07 Currently In Use	3959	2/1/1999 07 / No	Gasoline 4,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
8 / 08 Currently In Use	3960	2/1/1999 07 / No	Diesel 4,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
9 / 09 Currently In Use	3961	2/1/1999 07 / No	Gasoline 8,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Butte School Dist 1 1110 N Montana Butte MT 59701 Phone: (406) 533-2500

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4701980	Butte School Dist 1 Bus Barn	1220 E Front St	Butte	59701	(406) 496-2185

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
2 / 03 Currently in Use	1892	8/1/1992 13 / No	Diesel 10,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Safe Suction	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Ambrose Distributing Co 200 Lasalle St Butte MT 59702 Phone: (406) 736-5332

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4702689	Ambrose Distributing Co	La Salle St & S Dakota St	Butte	59701	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 05 Currently in Use	384	12/1/1991 14 / No	Diesel 10,000	Asphalt Coated or Bare Steel Impressed Current	Bare Steel Cathodically Protected	Safe Suction	<div style="display: flex; justify-content: space-between; padding: 2px;"> (A) (B) (C) (D) (E) (F) (G) (H) (I) (J) (K) (L) </div> <div style="display: flex; justify-content: space-between; padding: 2px;"> (B) (D) (E) (F) (G) (H) (I) (J) (K) (L) </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Cenex Petroleum Inc PO Box 64089 MS 535 Saint Paul MN 55164 Phone: (651) 355-5583

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4703979	Kum and Go Store 831	1759 S Montana St	Butte	59701	(406) 782-6509

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 05 Currently in Use	565	4/16/1991 15 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 06 Currently in Use	566	4/16/1991 15 / No	Diesel 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 07 Currently in Use	567	4/16/1991 15 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Morris Marketing Co 1480 Continental Dr Butte MT 59701 Phone: (406) 782-4255

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4705148	RDs Travel Stop	2801 Harrison Ave	Butte	59701	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 10 Currently in Use	1709	3/19/1990 16 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 11 Currently in Use	1710	3/19/1990 16 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 12 Currently in Use	1711	3/19/1990 16 / No	Diesel 6,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
8 / 08 Currently in Use	1707	3/19/1990 16 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
9 / 09 Currently in Use	1708	3/19/1990 16 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Edward G Lisac 2544 Harrison Ave Butte MT 59701 Phone: (406) 494-7056

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4705202	Lisacs Southside Exxon	2544 Harrison Ave	Butte	59701	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 07 Currently in Use	1547	3/8/1990 16 / No	Gasoline 10,000	Cathodically Protected Steel None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
7 / 06 Currently in Use	1546	3/8/1990 16 / No	Gasoline 10,000	Cathodically Protected Steel None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
8 / 09 Currently in Use	1549	6/1/1995 11 / No	Diesel 5,000	Fiberglass Reinforced Plastic None	Not Listed Cathodically Protected	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I J K <input checked="" type="radio"/></div> </div>	Yes Yes Yes Yes
9 / 08 Currently in Use	1548	6/1/1995 11 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Not Listed Cathodically Protected	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I J K <input checked="" type="radio"/></div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Hollow Construction 404 W Greenwood Ave Butte MT 59701 Phone: (406) 782-6033

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4705359	Hollow Construction	404 W Greenwood Ave	Butte	59701	(406) 782-6033

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
2 / 02 Currently in Use	4162	1/1/2000 06 / No	Diesel 15,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently in Use	4163	1/1/2000 06 / No	Diesel 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
4 / 04 Currently in Use	4164	1/1/2000 06 / No	Gasoline 5,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Hi Noon Petroleum PO Box 7578 Missoula MT 59807 Phone: (406) 532-0384

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4705772	Noons 421	2900 Harrison Ave	Butte	59701	(406) 494-6022

TankID/Alt TankID	Tag Numbe	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status		Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Over/C																								
1 / 01 Currently in Use	1369	11/14/1978 27 / No	Gasoline 12,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td></td><td></td><td></td><td>E</td><td>F</td><td></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C		E	F	G	H	I	J	K	L					E	F		H	I	J	K	L	Yes Yes Yes Yes
A	B	C		E	F	G	H	I	J	K	L																					
				E	F		H	I	J	K	L																					
2 / 02 Currently in Use	1370	11/13/1972 33 / No	Gasoline 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td></td><td></td><td></td><td>E</td><td>F</td><td></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C		E	F	G	H	I	J	K	L					E	F		H	I	J	K	L	Yes Yes Yes Yes
A	B	C		E	F	G	H	I	J	K	L																					
				E	F		H	I	J	K	L																					
3 / 03 Currently in Use	1371	11/13/1972 33 / No	Gasoline 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td></td><td></td><td></td><td>E</td><td>F</td><td></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C		E	F	G	H	I	J	K	L					E	F		H	I	J	K	L	Yes Yes Yes Yes
A	B	C		E	F	G	H	I	J	K	L																					
				E	F		H	I	J	K	L																					
4 / 04 Currently in Use	1372	11/13/1972 33 / No	Gasoline 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td></td><td></td><td></td><td>E</td><td>F</td><td></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C		E	F	G	H	I	J	K	L					E	F		H	I	J	K	L	Yes Yes Yes Yes
A	B	C		E	F	G	H	I	J	K	L																					
				E	F		H	I	J	K	L																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: St James Healthcare Inc 400 S Clark St Butte MT 59701 Phone: (406) 723-2500

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4706924	St James Healthcare Inc	400 S Clark St	Butte	59701	(406) 723-2500

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	FR Met
Status							Piping Release Detection	Spill/Overl/C
5 / 05 Currently In Use	4449	5/1/2001 05 / No	Diesel 15,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div><div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div><div>B D E F <input checked="" type="radio"/> H I J K L</div></div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Sutey Oil Co Inc 2000 Holmes Ave Butte MT 59701 Phone: (406) 494-2305

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4707932	Thriftway Super Stop 1	3501 Harrison Ave	Butte	59701	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 07 Currently in Use	2062	4/10/1990 16 / No	Gasoline 14,783	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Not Listed	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
8 / 10 Currently in Use	2065	4/10/1990 16 / No	Diesel 5,929	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Not Listed	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
9 / 11 Currently in Use	2066	4/10/1990 16 / No	Diesel 5,929	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Not Listed	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
10 / 08 Currently in Use	2063	4/10/1990 16 / No	Gasoline 11,627	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Not Listed	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> D E F G H I J K L</div> </div>	Yes Yes Yes Yes
11 / 09 Currently in Use	2064	4/10/1990 16 / No	Gasoline 11,627	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Not Listed	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Sutey Oil Co Inc 2000 Holmes Ave Butte MT 59701 Phone: (406) 494-2305

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4707934	Thriftway Super Stop 4	2610 Harrison Ave	Butte	59701	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
5 / 05 Currently in Use	2067	3/13/1990 16 / No	Gasoline 11,627	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Not Listed	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
6 / 06 Currently in Use	2068	3/13/1990 16 / No	Gasoline 11,627	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Not Listed	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
7 / 07 Currently in Use	2069	3/13/1990 16 / No	Gasoline 11,627	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Not Listed	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Sutey Oil Co Inc 2000 Holmes Ave Butte MT 59701 Phone: (406) 494-2305

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4707935	Thriftway Super Stop 2	1900 S Montana St	Butte	59701	(406) 782-5661

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
4 / 04 Currently in Use	2070	5/15/1989 17 / No	Gasoline 11,627	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
5 / 05 Currently in Use	2071	5/15/1989 17 / No	Gasoline 11,627	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
6 / 06 Currently in Use	2072	5/15/1989 17 / No	Gasoline 11,627	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Sutey Oil Co Inc 2000 Holmes Ave Butte MT 59701 Phone: (406) 494-2305

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4707936	Thriftway Super Stop 6	2401 Continental Dr	Butte	59701	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	2073	5/7/1968 38 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	2074	5/7/1968 38 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently in Use	2075	5/7/1973 33 / No	Gasoline 8,000	Asphalt Coated or Bare Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Butte Silver Bow 1700 Civic Center Road Butte MT 59701 Phone: (406) 723-8262

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4708477	Butte Silver Bow Maintenance Center	1700 Civic Center Road	Butte	59701	(406) 723-8262

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status				Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
6 / 06 Currently in Use	511	1/1/1997 09 / No	Gasoline 15,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
7 / 07 Currently in Use	512	1/1/1997 09 / No	Diesel 15,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4708679	Town Pump Inc Butte 1	1370 Harrison Ave	Butte	59701	(406) 782-4442

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C																								
1 / 08 Currently in Use	2621	7/28/1991 14 / No	Gasoline 4,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td></td><td></td><td></td><td>E</td><td>F</td><td></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C		E	F	G	H	I	J	K	L					E	F		H	I	J	K	L	Yes Yes Yes Yes
A	B	C		E	F	G	H	I	J	K	L																					
				E	F		H	I	J	K	L																					
2 / 07 Currently in Use	2620	4/11/1988 18 / No	Diesel 8,000	STI-P3 Impressed Current	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td></td><td></td><td></td><td>E</td><td>F</td><td></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C		E	F	G	H	I	J	K	L					E	F		H	I	J	K	L	Yes Yes Yes Yes
A	B	C		E	F	G	H	I	J	K	L																					
				E	F		H	I	J	K	L																					
3 / 06 Currently in Use	2619	4/11/1986 20 / No	Gasoline 8,000	STI-P3 Impressed Current	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td></td><td></td><td></td><td>E</td><td>F</td><td></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C		E	F	G	H	I	J	K	L					E	F		H	I	J	K	L	Yes Yes Yes Yes
A	B	C		E	F	G	H	I	J	K	L																					
				E	F		H	I	J	K	L																					
8 / 05 Currently in Use	2618	4/11/1988 18 / No	Gasoline 8,000	STI-P3 Impressed Current	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td></td><td></td><td></td><td>E</td><td>F</td><td></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C		E	F	G	H	I	J	K	L					E	F		H	I	J	K	L	Yes Yes Yes Yes
A	B	C		E	F	G	H	I	J	K	L																					
				E	F		H	I	J	K	L																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4708680	Town Pump Inc Butte 2	531 S Montana St	Butte	59701	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	2622	9/1/1985 20 / No	Gasoline 12,000	STI-P3 None	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	2623	9/1/1985 20 / No	Gasoline 12,000	STI-P3 None	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently in Use	2624	9/1/1988 17 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4708682	Town Pump Inc Butte 3	2328 S Montana St	Butte	59701	(406) 782-6758

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status				Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
3 / 04 Currently in Use	2626	10/1/1990 15 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>																					
4 / 05 Currently in Use	2627	10/1/1990 15 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>																					
5 / 06 Currently in Use	2628	10/1/1990 15 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table>	A	B	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	Yes Yes Yes Yes
A	B	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>																					
6 / 01 Currently in Use	2625	4/11/1981 25 / No	Diesel 12,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4708686	Town Pump Inc Butte 8	2001 Dewey Blvd	Butte	59701	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	2629	10/1/1981 24 / No	Gasoline 30,000	STI-P3 Impressed Current	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	No Yes Yes Yes
2 / 02 Currently in Use	4265	10/1/1981 24 / No	Gasoline 30,000	STI-P3 Impressed Current	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	No Yes Yes Yes
3 / 03 Currently in Use	2631	1/1/1977 29 / No	Gasoline 12,000	STI-P3 Impressed Current	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	No Yes Yes Yes
4 / 04 Currently in Use	2632	10/1/1981 24 / No	Diesel 12,000	STI-P3 Impressed Current	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	No Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4708687	Town Pump Inc Butte 10	901 N Excelsior Ave	Butte	59701	

TankID/Alt TankID	Tag	Installed	Product	Tank Mat'l of Construction	Piping Material		Tank Release Detection	FR Met																								
Status	Numbe	Age/AST	Capacity	Secondary Option	Secondary Option	Piping Type	Piping Release Detection	Spill/Overl/C																								
1 / 01 Currently in Use	2633	4/12/1971 35 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td>B</td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L		B		<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
	B		<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
2 / 02 Currently in Use	2634	4/12/1971 35 / No	Gasoline 4,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td>B</td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L		B		<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
	B		<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Qwest Communications 1600 7th Ave Room 2206 Seattle WA 98191 Phone: (206) 346-7532

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4708787	Qwest Butte Garage	1301 S Dakota St	Butte	59701	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
3 / 03 Currently in Use	1731	12/1/1992 13 / No	Gasoline 6,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Secondary Containment	Pressurized	<div style="display: flex; flex-wrap: wrap; padding: 2px;"> <div style="margin: 2px;">A B C D E F <input checked="" type="radio"/> H I J K L</div> <div style="margin: 2px;">B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Flying J Inc 1104 Country Hills Dr Ogden UT 84403 Phone: (801) 624-1295

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4709893	Flying J Inc Travel Plaza Rocker	112000 Rocker Interchange	Butte	59701	(406) 723-4325

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 02 Currently in Use	1100	11/8/1989 16 / No	Diesel 20,000	STI-P3 Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C ● E F G H ● J K L</div> <div>● ● E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently in Use	1101	11/8/1989 16 / No	Diesel 20,000	STI-P3 Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C ● E F G H ● J K L</div> <div>● ● E F G H I J K L</div> </div>	Yes Yes Yes Yes
4 / 04 Currently in Use	1102	11/8/1989 16 / No	Diesel 12,000	STI-P3 Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C ● E F G H I J K L</div> <div>● ● E F G H I J K L</div> </div>	Yes Yes Yes Yes
5 / 05 Currently in Use	1103	11/8/1989 16 / No	Gasoline 12,000	STI-P3 Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A ● ● ● E F G H I J K L</div> <div>● ● E F G H I J K L</div> </div>	Yes Yes Yes Yes
6 / 06 Currently in Use	1104	11/8/1989 16 / No	Gasoline 12,000	STI-P3 Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C ● E F G H I J K L</div> <div>● ● E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Silver Bow Petroleum Inc 4701 Harrison Ave Butte MT 59701 Phone: (406) 494-3803

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4710657	Norco Silver Bow Petroleum Express Lan	4701 Harrison Ave	Butte	59701	(406) 494-3803

TankID/Alt TankID	Tag Numbe	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status		Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
1 / 01 Currently in Use	1921	11/1/1987 18 / No	Gasoline 10,000	Cathodically Protected Steel None	Galvanized Steel Cathodically Protected	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr></table>	A	B	C	D	E	F	G	H	I	J	K	L													No Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					
2 / 02 Currently in Use	1922	11/1/1987 18 / No	Gasoline 10,000	Cathodically Protected Steel None	Galvanized Steel Cathodically Protected	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr></table>	A	B	C	D	E	F	G	H	I	J	K	L													No Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					
3 / 03 Currently in Use	1923	11/1/1987 18 / No	Gasoline 6,000	Cathodically Protected Steel None	Galvanized Steel Cathodically Protected	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr></table>	A	B	C	D	E	F	G	H	I	J	K	L													No Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					
4 / 04 Currently in Use	1924	11/1/1987 18 / No	Diesel 6,000	Cathodically Protected Steel None	Galvanized Steel Cathodically Protected	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr></table>	A	B	C	D	E	F	G	H	I	J	K	L													No Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Silver Bow County Public Works 126 W Granite Butte MT 59701 Phone: (406) 497-6521

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4713157	Silver Bow County Public Works	Browns Gulch	Butte	59701	

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
1 / 01 Currently in Use	4465	6/1/1993 13 / No	Diesel 12,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Safe Suction	<div> <div>A●CDEFG●HIJKL</div> <div>BDEFGHIJK●</div> </div>	<div> <div></div> <div></div> </div>	<div>Yes</div> <div>Yes Yes Yes</div>

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4713173	Town Pump Inc Rocker	1000 Grizzly Trl	Butte	59701	(406) 723-0088

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 10 Currently in Use	2644	6/1/1993 13 / No	Diesel 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> D E F G H <input checked="" type="radio"/> J K L</div> </div>	Yes Yes Yes Yes
2 / 11 Currently in Use	2645	6/1/1993 13 / No	Diesel 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H <input checked="" type="radio"/> J K L</div> </div>	Yes Yes Yes Yes
3 / 01 Currently in Use	2635	6/1/1993 13 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F <input checked="" type="radio"/> H <input checked="" type="radio"/> J K L</div> </div>	Yes Yes Yes Yes
4 / 07 Currently in Use	2641	6/1/1993 13 / No	Diesel 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> D E F G H <input checked="" type="radio"/> J K L</div> </div>	Yes Yes Yes Yes
5 / 08 Currently in Use	2642	6/1/1993 13 / No	Diesel 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> D E F G H <input checked="" type="radio"/> J K L</div> </div>	Yes Yes Yes Yes
6 / 09 Currently in Use	2643	6/1/1993 13 / No	Diesel 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H <input checked="" type="radio"/> J K L</div> </div>	Yes Yes Yes Yes
7 / 05 Currently in Use	2639	6/1/1993 13 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H <input checked="" type="radio"/> J K L</div> </div>	Yes Yes Yes Yes
8 / 06 Currently in Use	2640	6/1/1993 13 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H <input checked="" type="radio"/> J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

9 / 04 Currently in Use	2638	6/1/1993 13 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td><input checked="" type="radio"/></td><td>J</td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	<input checked="" type="radio"/>	J	K	L		Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	<input checked="" type="radio"/>	J	K	L																						
10 / 03 Currently in Use	2637	6/1/1993 13 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td><input checked="" type="radio"/></td><td>J</td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	<input checked="" type="radio"/>	J	K	L		Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	<input checked="" type="radio"/>	J	K	L																						
11 / 02 Currently in Use	2636	6/1/1993 13 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td><input checked="" type="radio"/></td><td>J</td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	<input checked="" type="radio"/>	J	K	L		Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	<input checked="" type="radio"/>	J	K	L																						
12 / 12 Currently In Use	4103	6/1/1999 07 / No	Diesel 8,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td>B</td><td><input checked="" type="radio"/></td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td><input checked="" type="radio"/></td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	<input checked="" type="radio"/>	B	<input checked="" type="radio"/>	D	E	F	<input checked="" type="radio"/>	H	<input checked="" type="radio"/>	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
<input checked="" type="radio"/>	B	<input checked="" type="radio"/>	D	E	F	<input checked="" type="radio"/>	H	<input checked="" type="radio"/>	J	K	L																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Morris Marketing Co 1480 Continental Dr Butte MT 59701 Phone: (406) 782-4255

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4713531	Morris Card Lock	16 Dewey Blvd	Butte	59701	(406) 782-4255

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	1712	8/1/1994 11 / No	Gasoline 20,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> D E F G H I J K L</div> <div><input checked="" type="radio"/> D <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	1713	8/1/1994 11 / No	Diesel 20,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> D E F G H I J K L</div> <div><input checked="" type="radio"/> D <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently in Use	1714	8/1/1994 11 / No	Diesel 20,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> D E F G H I J K L</div> <div><input checked="" type="radio"/> D <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
4 / 04 Currently in Use	1715	8/1/1994 11 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> D E F G H I J K L</div> <div><input checked="" type="radio"/> D <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
5 / 05 Currently in Use	1716	8/1/1994 11 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> D E F G H I J K L</div> <div><input checked="" type="radio"/> D <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
6 / 06 Currently in Use	1717	8/1/1994 11 / No	Diesel 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> D E F G H I J K L</div> <div><input checked="" type="radio"/> D <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
7 / 07 Currently in Use	1718	8/1/1994 11 / No	Diesel 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> D E F G H I J K L</div> <div><input checked="" type="radio"/> D <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Montana Resources Inc 600 Shields Ave Butte MT 59701 Phone: (406) 723-4081

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4713549	Montana Resources Inc	600 Shields Ave	Butte	59701	(406) 723-4081

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
2 / 02 Currently In Use	1687	10/1/1997 08 / No	Used Oil 6,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Gravity Feed	<div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	<div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Butte Aviation Inc 4602 Harrison Ave Butte MT 59701 Phone: (406) 494-6694

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4713713	Butte Aviation Inc	4602 Harrison Ave	Butte	59701	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	4663	12/1/1995 10 / No	Other 100	STI-P3 None	Galvanized Steel Plastic secondary contain	Gravity Feed	<div style="display: flex; justify-content: space-between; padding: 2px;"> <input checked="" type="radio"/> A <input type="radio"/> B <input type="radio"/> C <input type="radio"/> D <input type="radio"/> E <input type="radio"/> F <input type="radio"/> G <input type="radio"/> H <input type="radio"/> I <input type="radio"/> J <input type="radio"/> K <input type="radio"/> L </div> <div style="display: flex; justify-content: space-between; padding: 2px;"> <input type="radio"/> B <input type="radio"/> D <input type="radio"/> E <input type="radio"/> F <input type="radio"/> G <input type="radio"/> H <input type="radio"/> I <input type="radio"/> J <input checked="" type="radio"/> K <input type="radio"/> L </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613911	Town Pump Inc Butte 4	Elizabeth Warren St & Harrison Ave	Butte	59701	

TankID/Alt TankID	Tag Numbe	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																									
Status		Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																									
1 / 01 Currently In Use	4022	4/1/1999 07 / No	Gasoline 8,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>●</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td></td><td>D</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	●	E	F	●	H	I	J	K	L	B				D	E	F	●	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	●	E	F	●	H	I	J	K	L																						
B				D	E	F	●	H	I	J	K	L																					
2 / 02 Currently In Use	4023	4/1/1999 07 / No	Gasoline 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>●</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td></td><td>D</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	●	E	F	●	H	I	J	K	L	B				D	E	F	●	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	●	E	F	●	H	I	J	K	L																						
B				D	E	F	●	H	I	J	K	L																					
3 / 03 Currently In Use	4024	4/1/1999 07 / No	Gasoline 15,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>●</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td></td><td>D</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	●	E	F	●	H	I	J	K	L	B				D	E	F	●	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	●	E	F	●	H	I	J	K	L																						
B				D	E	F	●	H	I	J	K	L																					
4 / 04 Currently In Use	4025	4/1/1999 07 / No	Diesel 8,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>●</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td></td><td>D</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	●	E	F	●	H	I	J	K	L	B				D	E	F	●	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	●	E	F	●	H	I	J	K	L																						
B				D	E	F	●	H	I	J	K	L																					
5 / 05 Currently In Use	4026	4/1/1999 07 / No	Diesel 6,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>●</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td></td><td>D</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	●	E	F	●	H	I	J	K	L	B				D	E	F	●	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	●	E	F	●	H	I	J	K	L																						
B				D	E	F	●	H	I	J	K	L																					
6 / 06 Currently In Use	4294	4/1/1999 07 / No	Diesel 6,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>●</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td></td><td>D</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	●	E	F	●	H	I	J	K	L	B				D	E	F	●	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	●	E	F	●	H	I	J	K	L																						
B				D	E	F	●	H	I	J	K	L																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5614033	Northwest Petroleum Facility	28 Dewey Blvd	Butte	59701	(406) 497-6700

TankID/Alt TankID	Tag Numbe	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status		Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
1 / 01 Currently In Use	4639	4/17/2002 04 / No	Diesel 25,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Gravity Feed	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																							
2 / 02 Currently In Use	4640	4/17/2002 04 / No	Diesel 25,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Gravity Feed	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																							
3 / 03 Currently In Use	4641	4/17/2002 04 / No	Diesel 25,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Gravity Feed	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																							
4 / 04 Currently In Use	4642	4/17/2002 04 / No	Diesel 25,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Gravity Feed	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																							
5 / 05 Currently In Use	4643	4/17/2002 04 / No	Diesel 25,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Gravity Feed	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																							
6 / 06 Currently In Use	4644	4/17/2002 04 / No	Diesel 25,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Gravity Feed	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																							
7 / 07 Currently In Use	4645	4/17/2002 04 / No	Diesel 25,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																							
8 / 08 Currently In Use	4646	4/17/2002 04 / No	Diesel 25,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Gravity Feed	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																							

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Qwest Communications 1600 7th Ave Room 2206 Seattle WA 98191 Phone: (206) 346-7532

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5614034	Qwest Butte Main Central Office	200 W Broadway St	Butte	59701	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently In Use	4732	10/2/2002 03 / No	Diesel 2,500	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Safe Suction	<div style="display: flex; justify-content: space-between; padding: 2px;"> (A) (B) (C) (D) (E) (F) (G) (H) (I) (J) (K) (L) </div> <div style="display: flex; justify-content: space-between; padding: 2px;"> (B) (D) (E) (F) (G) (H) (I) (J) (K) (L) </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Butte Silver Bow 1340 Harrison Ave Butte MT 59701 Phone: (406) 497-6402

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5614119	Detention Center	155 W Quartz St	Butte	59701	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently In Use	5006	1/31/2005 01 / No	Diesel 1,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div style="display: flex; justify-content: space-between; padding: 2px;"> (A) (B) (C) (D) (E) (F) (G) (H) (I) (J) (K) (L) </div> <div style="display: flex; justify-content: space-between; padding: 2px;"> (B) (D) (E) (F) (G) (H) (I) (J) (K) (L) </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Morris Marketing Co 1480 Continental Dr Butte MT 59701 Phone: (406) 782-4255

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613959	RDs Quick Fuel Divide	Interstate 15	Divide	59727	(406) 494-8805

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / S1 Currently In Use	4121	9/1/1999 06 / Ye	Gasoline 12,000	Asphalt Coated or Bare Steel Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Silver Bow

Owner Name and Address: Lively Inc PO Box 96 Melrose MT 59743 Phone: (406) 835-2721

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4707486	Melrose Bar Service Station Post Office	110 Main St	Melrose	59743	(406) 835-2711

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C																										
1 / 01 Currently In Use	4054	5/8/1983 23 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="3">B</td><td colspan="3">D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><input checked="" type="radio"/></td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B			D			E	F	G	H	I	<input checked="" type="radio"/>	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																							
B			D			E	F	G	H	I	<input checked="" type="radio"/>	K	L																					
2 / 02 Currently In Use	4055	5/8/1983 23 / No	Diesel 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="3">B</td><td colspan="3">D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><input checked="" type="radio"/></td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B			D			E	F	G	H	I	<input checked="" type="radio"/>	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																							
B			D			E	F	G	H	I	<input checked="" type="radio"/>	K	L																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed